

Part-1

**Performa For The Safety School Building
(To be filled by the Head of School / Institute) .**

1. Name of school Green Land Convent School
2. Location Sector -32, Chandigarh Road, Ludhiana
3. Plot Area 7260 sq.yard
4. Plinth Area 6000 sq.yard (Six thousand square yard)
5. Number of Storey Basement/ Ground/ First/Second/Third
6. Year of Construction of building 2007
7. Supervision of the qualified Engineer,

The following details may be given:

- a) Name of the Engineer Mr. Verinder Kumar (Civil Engineer)
b) Address B-IV,1132 Daresi Road, Ludhiana
c) Set of Structure Drawing used in the
Construction if available Enclosed
d) Name of the Architect Mrs. Shelja Gupta

8. Whether the building has been constructed for the purpose of:

- a) School (Yes / No) Yes
b) Residential purpose and converted
for use as a school (Yes / No) No

9. Materials used for Roof:

- a) R.C.C. slabs (Yes / No) Yes
b) R.S. Joists and Battens (Yes / No) No
c) Wooden Joists and Battens (Yes / No) No

10. Materials used for walls:


- a) Mud Mortar (Yes / No) No
b) Cement Mortar (Yes / No) Yes
c) Plaster (i) Lime Mortar (Yes / No) No
(ii) Cement Mortar (Yes / No) Yes

11. Flooring:

- a) Conglomerate (Yes / No) Yes
b) Terrazzo (Yes / No) No
c) Brick Paving (Yes / No) No

12. Detailed Drawing indicating dimensions
of the rooms along with size and location
of doors and windows

Enclosed


Principal
Green Land Convent School
Ludhiana.
Signature with stamp of
The Head of the School / Institute

D/2023-24/ 59

dt 16/5/2023
PART-II
(To be filled by the S.D.E.)

a) I have visited the above mentioned school on dated 08/05/2023..... and have visually inspected it from all angles of safety and find it fit for normal use as School buildings.

b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.

c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.

d) This building can be safety occupied for normal use upto 31/03/2024
(indicate upto which it can be used)

Amblom
Sub Divisional Engineer,
Provincial Sub Division No. 3,
P.W.D. B&R, Br. LUDHIANA.

Amblom
Sub Divisional Engineer