

Part-1

**Performa For The Safety School Building
(To be filled by the Head of School / Institute)**

1. Name of school Green Land Convent School
2. Location Sector -32, Chandigarh Road, Ludhiana
3. Plot Area 7260 sq.yard
4. Plinth Area Basement: 3000 sqft , G.F.:31800 sqft, 1st Floor:31800
2nd Floor: 31800 sqft , 3rd Floor:31800 Sqft, 4th Floor:3000 sqft
Total Area:133200 sqft
5. Number of Storey Basement/ Ground/ First/Second/Third
6. Year of Construction of building 2007
7. Supervision of the qualified Engineer,
The following details may be given:
- a) Name of the Engineer Mr. Ved Bhushan Sharma (Civil Engineer)
- b) Address Abuwal Road, New Abadi Akalgarh, Ludhiana
- c) Set of Structure Drawing used in the
Construction if available Enclosed
- d) Name of the Architect Mrs. Shelja Gupta
8. Whether the building has been constructed for the purpose of:
- a) School (Yes / No) Yes
- b) Residential purpose and converted
for use as a school (Yes / No) No
9. Materials used for Roof:
- a) R.C.C. slabs (Yes / No) Yes
- b) R.S. Joists and Battens (Yes / No) No
- c) Wooden Joists and Battens (Yes / No) No
10. Materials used for walls:
- a) Mud Mortar (Yes / No) No
- b) Cement Mortar (Yes / No) Yes
- c) Plaster (i) Lime Mortar (Yes / No) No
- (ii) Cement Mortar (Yes / No) Yes
11. Flooring:
- a) Conglomerate (Yes / No) Yes
- b) Terrazzo (Yes / No) No
- c) Brick Paving (Yes / No) No
12. Detailed Drawing indicating dimensions
of the rooms along with size and location
of doors and windows Enclosed

Signature with stamp of
Principal
Green Land Convent School
The Head of the School / Institute
Ludhiana,

Part-II


(To be filled by S.D.E of P.W.D. B & R Department)

I have visited the above mentioned school on 03/07/24 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safely occupied for normal use up to 31/03/25 (indicate year up to which it can be used).


Sub-Divisional Engineer
ਪ੍ਰਾਚਕ ਉਪ ਮੰਡਲ ਨੰ. 3,
ਲੋ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਲੁਧਿਆਣਾ

